Contact our sales office regarding a delivery date or a price since this is a special model.



SP137X-030E RP : SQ

SMC CORPORATION 4-14-1,SOTO-KANDA, CHIYODA-KU,

TOKYO 101-0021, JAPAN URL: http://www.smcworld.com

Markless Pad for Thin Plate


ZP-697Series

Prevention of workpiece deformation during adsorption Suitable for adsorption and transfer of solar panels or glass substrates


Prevention of workpiece deformation

A breathable non-woven cloth plate that allows a flat adsorption surface.

Prevention of workpiece deformation during adsorption



Markless Pad for Thin Plate




General cup shaped pad

A workpiece may be deformed or damaged along the pad shape.

Reduced adsorption marks on workpiece

The surface that comes into contact with a workpiece is made of a non-woven cloth plate and resin film to prevent components from being transferred to the workpiece.





Ease of maintenance improved

The non-woven cloth plate and rubber seal are replaceable.


Application

Adsorption and transfer of solar power panels






How to Order




Dimensions(mm)

Female thread connection type

Ф50 : ZP-697-50NHB14 [Weight:88.5g]







Ф80 : ZP-697-80NHB14 [Weight:180.8g]

Male thread connection type

Ф50 : ZP-697-50NHA14 [Weight:130g]



Ф80: ZP-697-80NHA20 [Weight:230g]



 $_{\Delta}$ Caution To ensure the safest possible operation of this product, please be sure to thoroughly read the "Safety Instructions" in our "Best Pneumatics" catalog before use.